

Please complete every section daily and give to at ENV Station 001.

Date: 6/19/17

Time: 10:25 a.m

Initials: TRB

Outfall 009/010	Answers
Substance discharged?	Y / (N)
-If Yes, Color?	-
-If Yes, Size / Area?	-
Vac truck amount recovered	100 Gallons
Estimated oil recovered	Trace oil
Length of sorbent boom replaced	0
Canal Appearance (winds, sheen, etc.)	Light, < 5 mph SW

Date: 6/19/17

Time: 10:15 a.m

Initials: TRB

Outfall 001	Answers
Substance discharged?	Y / (N)
-If Yes, Color?	-
-If Yes, Size / Area?	-
Vac truck amount recovered	200 Gallon
Estimated oil recovered	≈ 5 gallons
Length of sorbent boom replaced	100' in shoe belt &
Canal Appearance (winds, sheen, etc.)	Light, < 5 mph, SW

* One replaced absorbent Shetty